

FIGURES




Fig. 1




Fig. 2




Fig. 3




Fig. 4






Fig. 6a




Fig. 6b




Fig. 8a




Fig. 8b




Fig. 10




Fig. 11








Fig. 9





24-11-889
















Fig. 7






Fig. 12




Fig. 13




Fig. 14




Fig. 15




Fig. 16




Fig. 17




Fig. 18





Fig. 19



0 10 20 30 40 50




Fig. 20




Fig. 21




Fig. 22




Fig. 23a




Fig. 23c




Fig. 23b







Fig. 24




*Back corner post on right.
1372+1373
bottom.*



Floor beam at back.

1374—Right Hand Corner.



*Floor beam at right.
Right Beam 1407—Back End
Tenon b.
& Socket c.*

Fig. 25




Fig. 26




Fig. 27




Fig. 28a






Fig. 28b



0 1 2 3 4 5 6 7 8 9 10



Fig. 29a







Fig. 29b



Fig. 30



0 10 20 30 40 50cm.





Fig. 31




Fig. 32